

FIRMWARE RELEASE NOTES



Model	Chameleon CTM-15X modem
Revision:	#2023.0045 Revision 1.1.29_2

3066 Beta Avenue Burnaby, B.C. V5G 4K4
Phone: 604.294.4465
Fax: 604.294.4471
support@cypress.bc.ca

1 1 Contents

1	1 Contents.....	2
2	Revision Control.....	2
3	Release Notes for the CTM-15X Modem Firmware (Rev 1.1.29_2).....	2
3.1	R1.1.29_2 Changes.....	2
3.2	R1.1.25 Changes.....	3
3.3	R1.1.24 Changes.....	3
3.4	R1.1.23 Changes.....	3
3.5	R1.1.21 Changes.....	4
3.6	R1.1.20 Changes.....	4
4	Technical Support/Warranty:	4

2 Revision Control

Description	Revision	Date
Customer Release	#2023.0045 Revision 1.1.29_2	4-Mar-2008

3 Release Notes for the CTM-15X Modem Firmware (Rev 1.1.29_2)

This release note provides an overview of the features in the CTM-15x embedded firmware release.

3.1 R1.1.29_2 Changes

New Features:

- Added Wireless Number Portability (WNP)
- Over The Air Provisioning (OTASP)
- PRL upgrade capability
- Added a new report message (Message 40)
- New command to show modem configuration (showconfig)

Fixes:

- PWRWOE timer issue fix
- Local PPP disconnects
- Pass through mode for UDM tool
- Panic button message issues
- Disabled modem synchronization to the CDMA network time

3.2 R1.1.25 Changes

New Features:

- Network watchdog added. New command - **netwd**
- Modem synchronization to CDMA network time

Fixes:

- Store and forward out of coverage detection

3.3 R1.1.24 Changes

New Features:

- none

Fixes:

- The system log file has a finite size so that it does not use up too much of the RAM
- Verify that flash config file exists before saving to FLASH to prevent the modem's configurations from being corrupted.

3.4 R1.1.23 Changes

New Features:

- New commands to change the web and telnet passwords – **telnetpswd** and **webpswd**
- New commands to add and delete messages associated with the PANIC message for the Work Alone system – **zbeeaddmes**, **zbeedelmes**, and **zbeemes**

Fixes:

- "cmd ratetmr"; for the AC595, the modem was not trying to reconnect to EVDO when in 1x
- PAD – In PAD, an escape character was being discarded even though it may not have been a real escape sequence
- Zigbee does not require a valid IP address as a condition to start working
- Updated firmware so that during boot up, the firmware upgrade feature does not write to FLASH

3.5 R1.1.21 Changes

New Features:

- None

Fixes:

- Factory reset – mode will default to 2 (auto connect); previously the default was 1
- Packet sizes of more than 1500 bytes would cause an issue on the Ethernet port

3.6 R1.1.20 Changes

New Features:

- Updated embedded web pages with a new brand interface
- New Port Forwarding feature with the ability to map an external port to a different local port
- Added additional PAD modes (2 – 7)
- New OBD NMEA messages (POBDB – POBDF)

Fixes:

- TCP PAD recovery if the IP address is refreshed
- “cmd port”; when baud rate is changed from 115200, modem responses will be visible after a power cycle
- GPS stationary heading change fixed
- Fixed throttle position in the POBDA message (missing in previous version)
- DNS server fixed so that web site names can be probably mapped to an IP address
- TCP local and remote reporting fixed

4 Technical Support/Warranty:

Cypress Solutions Service**Support Group**

1.877.985.2878 or 604.294.4465

9.00am to 5.00pm PST

support@cypress.bc.ca