

Firmware Release Notes

Model	CTM-500
Version	1.5.4

Firmware Release Notes: CTM-500 3066 Beta Avenue | Burnaby, B.C. | V5G 4K4 © 2023 Cypress Solutions

Version 1.5.4

Release Date

• Nov 30, 2023

Note : Downgrades from version 1.5.0 and above are not supported

Features and Improvements

- QoS
- Dual SIM Failover
- Support for CTM Connect GATT Endpoint
- LED flashing while booting
- Calculation of GPS SQI

Bug Fixes

- Improved resiliency of OTA FW Upgrades
- CAN_STATUS key state not correct with CAN disabled
- NET_ETHO_LINK key state not indicating Ethernet disconnected
- Device not aborting LPM if ignition comes back
- Setting interface metric for DHCP client interfaces
- CTM-500 WIFI driver update
- Automatic deletion of feature log files when disabling log in the configuration
- Improper handling of DNS when switching SIM slots
- Pass through static Routing between devices on the same subnet
- Spreader support updated to 1.7.1.fw CIRUS material name fix

Technical Support





1.877.985.2878 or 1.604.294.4465 9.00am to 5.00pm PST support@cypress.bc.ca

